



Tersus David GNSS Receiver Firmware Version (FW0307)

Release

Jul 08, 2019

Overview

Tersus GNSS Inc. ("Tersus") is glad to release the firmware to David GNSS receiver. Firmware version (FW0307) is available for download at www.tersus-gnss.com/software/david-receiver and support documents are available at www.tersus-gnss.com/document.

Features

- The firmware tracks three constellations: GPS (L1/L2), GLONASS (L1/L2) and BeiDou (B1/B2).
- This firmware provides centimeter-level accurate positioning to meet the wide range of precision positioning applications. Even in harsh environments and long baseline (15~30km) situation, the fixed RTK solutions can satisfy the diversity of surveying needs.
- The 4 GB onboard data storage makes it possible to store raw measurements for post-processing application.
- The maximum update rate is 20Hz for RTK and 20Hz for raw measurements.
- With a number of configurations, the firmware matches the needs for post-processing workflows, and for the use as a base/rover station or rover.

Change from Previous Versions

Issue	Type	FW
Fix the bug of RTCM2 decoding.	Bug Fix	FW0307
Fix the bug of 'log undulation'	Bug Fix	FW0306

Information and related materials are subject to change without notice. ©Copyright 2018 Tersus GNSS Inc.

Technical Support: support@tersus-gnss.com Website: www.tersus-gnss.com

Increase the number of decimal places for latitude and longitude std for log gpgst and log bestpos.	Bug Fix	FW0278
Fix a convert GLONASS ephemeris time bug.	Bug Fix	FW0268
Fix the bug of ephemeris log.	Bug Fix	FW0259
Fix the bug of SATVIS log.	Bug Fix	FW0243
Make the 'rtkcommand reset' work.	Bug Fix	FW0179
Baseband fix a Time Quality upgrade without firstly set time possible bug.	Bug Fix	FW0173
Switch back AP RTK callback calling order	Bug Fix	
Make synchronous logs have priority over asynchronous	Bug Fix	
Add antenna type field in "thisantenna" log and this information can be converted to RINEX header.	Enhancement	
Change FSBL	Enhancement	
Fixed the GLONASS string count=0 problem which would cause GLONASS have no observations when the UTC time equals 3 a.m.	Bug fix	FW0138
Expanded the size of RTK ephemeris array. This problem would cause the newly raised GPS satellites not to participate in RTK solution.	Bug fix	
Fixed the problem of ionospheric model jumping.	Bug fix	
Added the function of smoothing RTK solution to get POSAVE coordinates.	Enhancement	
Fixed the bug of RTCM3 encoding and decoding of FW0114	Bug fix	FW0131
If the input coordinates and actual coordinates	Enhancement	FW0114

differ by more than 30m in one direction,it will stop broadcasting RTCM messages although the RTCM logs are input.		
The RTK engine is updated.	Enhancement	
Optimized cycle slip detecting method.	Enhancement	FW0089
Fixed the problem of invalid 'RTKSOURCE' command.	Bug fix	FW0086
When input have TAB (it maybe copy from pdf,html..etc.). Make Response enable.	Enhancement	
The RTCM date will be broadcast only when the coordinates are fixed.	Bug fix	FW0082
Changed the RTCM1230 encoding and RTCM1033 decoding.	Bug fix	
AP added more checks for response.	Enhancement	
Make file downloads more robust.	Enhancement	
Fixed the bug of Galileo and BeiDou sig mask and GPS and GLONASS sig mask.	Bug fix	
Add DAC control clock drift range protection to +/- 0.6 ppm	Enhancement	
Consider clock drift error at recover clock drift stage.	Enhancement	
Expand clock drift recover range to 15Hz and expand clock drift tuning range to 40Hz.	Enhancement	
The RTK engine is updated to version 3.0 which is more stable re reliable.	Enhancement	
Fixed the bug of log GPHDT.	Bug fix	FW0026
Fixed the bug of log cmrplus/cmrdes	Bug fix	
Fixed the problem that sometimes USB can't be connect to the David Receiver.	Bug fix	

Fixed the bug when the updating is not successful.	Bug fix	FW0025
Changed the naming method of storage files. The time when the file was created is taken as the file name.	Enhancement	
Added a new feature of [base network]. (refer to < User Manual For BX Series GNSS Receiver >, 2.6.1)	Enhancement	FW0024
The update logical has been optimized.	Enhancement	
The logic of firmware update has been optimized.	Enhancement	FW0023
The USB feature of firmware has been optimized.	Enhancement	
Log GPZDA may cause the FW not working.	Bug Fix	FW0022
The error rate of serial port input and output data is reduced.	Enhancement	